

# MICHELIN TECHNICAL BULLETIN

May 31, 2005  
Updated Oct. 2017

## X One® XZU®S Repair Recommendations

The purpose of this Technical Bulletin is to define the X One® XZU®S repair recommendations.

The X One® XZU®S is optimized for use in sanitation fleets. This usage is defined as a Severe Use Application therefore the same repair specs that apply to the XZU®S2 also apply to the X One® XZU®S.



### Severe Use Application

Nail Hole Repairs	Size		Section Repairs in the Crown Area	Quantity
	Section Repairs in the Sidewall Area			
10 mm diameter	L	W	40 mm	9 See Notes Below
	80 mm	40 mm		
	or			
	100 mm	30 mm		
	or			
130 mm	20 mm			
or				
150 mm	1 cable			

L = Length in radial direction

W = Length in circumferential direction

*NOTE: Limit for Severe Use represents a total of section and nail hole repairs for both crown and sidewall combined. Refer to radial repair chart to select proper size of repair unit.*

For additional information please contact your local Michelin sales representative or contact Michelin using the website at [www.michelintruck.com](http://www.michelintruck.com).

[www.michelintruck.com](http://www.michelintruck.com)

MICHELIN NORTH AMERICA, INC., Greenville, South Carolina, USA  
MICHELIN NORTH AMERICA (CANADA) INC., Laval, Quebec, Canada  
MICHELIN MEXICO S.A. DE C.V., Mexico City, Mexico

An Equal Opportunity Employer

© 2017 MNA, Inc. (10/17)

