

Michelin Technical Bulletin

May 31, 2005
Updated Oct. 2017

X One® XZU®S Repair Recommendations

The purpose of this Technical Bulletin is to define the X One® XZU®S repair recommendations. The X One® XZU®S is optimized for use in sanitation fleets. This usage is defined as a Severe Use Application therefore the same repair specs that apply to the XZU®S2 also apply to the X One® XZU®S.



Severe Use Application

Size			Quantity
Nail Hole Repairs	Section Repairs in the Sidewall Area		Section Repairs in the Crown Area
10 mm diameter	L	W	40 mm
	80 mm	40 mm	9
	or		See Notes Below
	100 mm	30 mm	
	or		
	130 mm	20 mm	
	or		
	150 mm	1 cable	

L = Length in radial direction

W = Length in circumferential direction

NOTE: Limit for Severe Use represents a total of section and nail hole repairs for both crown and sidewall combined.

Refer to radial repair chart to select proper size of repair unit.

For additional information, please contact your local Michelin sales representative or contact Michelin using the website at US : business.michelinman.com or CA : www.michelintruck.com/en_CA.

US : business.michelinman.com

CA : www.michelintruck.com/en_CA

MICHELIN NORTH AMERICA, INC., Greenville, South Carolina, USA
MICHELIN NORTH AMERICA (CANADA) INC., Laval, Quebec, Canada

An Equal Opportunity Employer.

Copyright ©2021 Michelin North America, Inc. All rights reserved. PDF ONLY (06/21)



MICHELIN